

Reliability

= f

material composition, design parameters,
operating stresses, environmental
conditions, customer usage, system
integration, interfaces between parts, etc.

Measure,
monitor,
calculate

Define, adjust or control
the factors that influence
the design, environment
or customer usage

Question:

Where should the focus be to improve reliability?

The left or the right side of the equation?